

1 IN THE DRAWINGS:

2 Enclosed with this response are three replacement drawing sheets. These replacement
3 drawing sheets replace originally filed drawing sheets 2, 3, and 4. The changes in these
4 replacement sheets address the Examiner's objections to the drawings. Specifically, in Figure 2,
5 the value associated with V2 is changed to 0.5325v. In Figure 4, the value associated with V2 is
6 also changed to 0.5325v and V1 is added next to the 1.25v input to differential receiver 402. In
7 Figure 6, reference numeral 618 is added to identify the inverter for signal B.

8

Appl. No. 09/640, 802
 Amdt. Dated 05-15-2004
 Reply to Office action of Feb. 23, 2004

2/5

Replacement Sheet




FIG. 2




FIG. 3

Appl. No. 09/640, 802
 Amdt. Dated 05-15-2004
 Reply to Office action of Feb. 23, 2004

3/5

Replacement Sheet




FIG. 4




FIG. 5

Appl. No. 09/640, 802
 Amdt. Dated 05-15-2004
 Reply to Office action of Feb. 23, 2004

4/5

Replacement Sheet

FIG. 6

